

Furthermore the opening must be plumb and square.

Units in mm			
W	Opening width		
Н	Opening height		
F	Free room above lintel		550
Α	Height of shaft above lintel		420
L	Free side room left		0
R	Free side room right		0
D	Back room length of horizontal track	H+530	
Х	1st hanging point		700
Υ	2nd hanging point	½ Dx	
Y2	3rd hanging point	2/3 Dx	
Z	4th hanging point		300
Q	Free space depth (back room)	D+400	
S	Shaft Axis over Floor	(H+A)	
L/R	Position of motor		min. 400

## **Interior view**

Work to be carried out by customer, unless in advance otherwise Necessary free room is agreed in writing.

Necessary mounting surface



Mounting surface for motor (L or R)

Supply and fix mounting frame and mounting surfaces for the rails

and the spring packet in case of aerated concrete or sandwichpanels etc.

Necessary mounting surface and free room as shown.

Electrical supply required to be: Industrial electric outlet cee 20A, 5P, 400 V, protected by 20A circuit breaker, residual current device I=30 mA.

Revision date 04.01.2023

Sheet:

А3

Version: 2309